



3rd September 2014

BJ/SH-L2/ 146

BSE Limited
Corporate Relationship Department
1st Floor, New Trading Ring
Rotunda Bldg, P. J. Towers
Dalal Street, Fort
Mumbai – 400 001.

National Stock Exchange of India Limited
Exchange Plaza, 5th Floor
Plot No. C/1, G Block
Bandra-Kurla Complex
Bandra (East)
Mumbai – 400 051.

Dear Sirs,

Tripping of Unit No.5 at Trombay

On 2nd September 2014, at 09:45 hours, the Mumbai power supply was affected due to tripping of Unit No.5 of 500 MW capacity at Trombay Power Station due to technical fault. Immediately, after tripping of the 500 MW unit, partial load was restored through enhanced generation from the Company's hydro stations and the Company activated the initialization activities of its cold standby Unit No.6, which runs on oil and was kept on cold standby as per directive of the procurers.

While Unit No.5 restoration work is still under progress, Unit No.6 (also 500 MW), which was on cold stand-by has been synchronized and is generating. There has been NO load shedding after about 9.00 p.m. While the power was available in neighbouring areas of Maharashtra considering rainy season, however, due to overloading of state transmission network, the distribution companies were not able to import power for Mumbai. The distribution companies did a rotational load shedding in their respective areas of about 200-300 MW during 9.45 a.m. to 9 p.m. The Mumbai load has been fully restored and power normalized fully.

We would like to underline Tata Power's commitment to providing reliable and 24x7 quality power to the city of Mumbai.

Yours faithfully,
For The Tata Power Company Limited

(H. M. Mistry)
Company Secretary

TATA POWER

The Tata Power Company Limited

Registered Office Bombay House 24 Homi Mody Street Mumbai 400 001

Tel 91 22 6665 8282 Fax 91 22 6665 8801

Website : www.tatapower.com Email : tatapower@tatapower.com CIN : L28920MH1919PLC000567