

Regd. Office: P.O. Duliajan, Dist. Dibrugarh, Assam-786602 Corp Office: Plot No. 19, Sector 16-A, Noida-201301, Uttar Pradesh CIN: L11101AS1959GOI001148 Website: www.oil-india.com

Ref. No. OIL/SEC/32-33/NSE-BSE

Dated: 10.04.2024

National Stock Exchange of India Limited

Exchange Plaza, Plot No. C/1, G Block, Bandra Kurla Complex, Bandra (E), Mumbai - 400 051

NSE Symbol: OIL

BSE Limited

Department of Corporate Service Phiroze Jeejeebhoy Towers Dalal Street Mumbai - 400 001

BSE Security Code: 533106

Sub: Press Release - Incident at BGN#24

Ref. : Regulation 30 of SEBI [Listing Obligations & Disclosure Requirements

(LODR)] Regulations, 2015

Sir / Madam,

Pursuant to Regulation 30 of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015, Press Release dated 10.04.2024 on the captioned subject is submitted for your information & records please.

Thanking you,

Yours faithfully, For Oil India Limited

A.K. Sahoo Company Secretary & Compliance Officer



ऑयल इंडिया लिमिटेड Oil India Limited A Maharatna CPSE email – oilindia@oilindia.in Website – <u>www.oil-india.com</u>



FOR IMMEDIATE RELEASE April, 10, 2024

Incident at BGN#24

An incident of leakage was reported at the X-Mass Tree of well no. BGN#24, located at Dighaltarang Tea Estate, Tinsukia District in Assam at around 11:30 pm on 09.04.2024.

OIL personal rushed to the site and controlled the leak at around 2:20 am today. The District Administration was informed and officials from the Administration was present at site to assess and address the situation. Proactively, fire service was mobilised, and fire service crew is kept stand by.

Upon examination, a hole was observed on the flow path from the X-mass tree and the same is under investigation. Gas and crude oil had spread out over nearby areas located within approximately 100 m from the wellsite. An on-site assessment team of OIL is formed to assess the affected areas immediately. The OIL team is taking up measures for remediation of the affected area.

An internal enquiry is being conducted for a thorough investigation and OIL reassures that the well is in completely controlled & closed condition and there is no point of panic for the same.

















