

हिन्दुस्तान कॉपर लिमिटेड HINDUSTAN COPPER LIMITED

www.hindustancopper.com

CIN: L27201WB1967GOI028825



No. HCL/SCY/SE/ 2023

The Sr. General Manager
Dept. of Corporate Services
BSE Limited
Phiroze Jeejeebhoy Towers
Dalal Street
Mumbai 400 001
BSE Scrip Code: 513599

Date: 15th May, 2024

The Vice President
Listing Department
National Stock Exchange of India Ltd
Exchange Plaza, C-1, Block G
Bandra-Kurla Complex, Bandra (East)
Mumbai 400 051
NSE Symbol: HINDCOPPER

Sir/Madam,

Subject: Accident on 14.5.2024 at Kolihan Copper Mine of Khetri Copper Complex, a unit of Hindustan Copper Ltd

It is informed that an accident occurred at Kolihan Copper mine of Khetri Copper Complex, Khetrinagar, Rajasthan (a unit of Hindustan Copper Ltd) at around 7:30 PM on 14.5.2024.

Due to rope snapping and collision of cage at pit bottom buffer resulted in an accident during man winding. This caused one fatal and fourteen persons were suffered with serious bodily injury. The Company is taking all steps to bring normalcy and resume operations.

The above is submitted pursuant to Regulation 30 of SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015 for information and record please.

Thanking you,

Yours faithfully,

(C S Singhi) Company Secretary & Compliance Officer