



September 24, 2024

BSE Limited
Corporate Relationship Department
Phiroze Jeejeebhoy Towers
Dalal Street
Mumbai – 400 001.
Scrip Code: 500400

National Stock Exchange of India Limited
Exchange Plaza, C-1, Block G,
Bandra-Kurla Complex,
Bandra (East)
Mumbai – 400 051.
Symbol: TATAPOWER

Dear Sir/Madam,

Disclosure under Regulation 30 of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015

Pursuant to Regulation 30 of the Securities and Exchange Board of India (Listing Obligations and Disclosure Requirements) Regulations, 2015, as amended, we hereby inform you that there was a fire incident in the Control Room of Unit No. 5 (500 MW unit) of Trombay Plant on September 23, 2024. The cause of the fire is currently under investigation, and no injuries or loss of life have been reported.

The Company is in the process of assessing the actual damage caused by the fire. We also confirm that the plant is adequately insured, and the Insurance Company has been duly informed. Efforts are underway to restore normal operations at the plant as soon as possible.

Further updates will be provided in due course.

This is for your information and records.

Yours Sincerely,
For The Tata Power Company Limited

Vispi S. Patel
Company Secretary
FCS 7021

TATA POWER

The Tata Power Company Limited

Registered Office Bombay House 24 Homi Mody Street Mumbai 400 001

Tel 91 22 6665 8282 Fax 91 22 6665 8801

Website : www.tatapower.com Email : tatapower@tatapower.com CIN : L28920MH1919PLC000567