

MSIL: COS: NSE&BSE: 2022/04_05

06th April, 2022

Vice President

National Stock Exchange of India Limited

"Exchange Plaza", Bandra- Kurla Complex

Bandra (E)

Mumbai - 400 051

General Manager

Department of Corporate

Services BSE Limited

Phiroze Jeejeebhoy Towers Dalal

Street, Mumbai- 400 001

Sub: Press Release

Dear Sir/Madam,

Please find enclosed herewith as Annexure -"A", a copy of the press release being issued today.

Kindly take the same on record.

Thanking you,

Yours truly,

For, Maruti Suzuki India Limited



Sanjeev Grover

Executive Vice President

& Company Secretary

MARUTI SUZUKI INDIA LIMITED

Head Office:

Maruti Suzuki India Limited,

1, Nelson Mandela Road, Vasant Kunj,

New Delhi - 110070, India.

Tel: 011- 46781000, Fax: 011-46150275/46150276

E-mail id: contact@maruti.co.in, www.marutisuzuki.com

Gurgaon Plant:

Maruti Suzuki India Limited,

Old Palam Gurgaon Road,

Gurgaon - 122015, Haryana, India. Tel:

0124-2346721, Fax: 0124-2341304

Manesar Plant:

Maruti Suzuki India Limited,

Plot No.1, Phase - 3A, IMT Manesar,

Gurgaon - 122051, Haryana, India. Tel:

0124-4884000, Fax: 0124-4884199

Press Release

Maruti Suzuki to proactively recall 19,731 units of EECO

To check and correct the rim size information marked on the wheel

New Delhi, 6th April 2022: Maruti Suzuki India Limited ('Maruti Suzuki') has announced to proactively and voluntarily recall 19,731 units of its EECO model. The recall is being undertaken to inspect and rectify 'incorrect marking of wheel rim size', if any, on the wheel in some of these vehicles.

In a routine inspection, Maruti Suzuki found that in some units of EECO, manufactured between 19th July 2021 and 5th October 2021, the wheel rim size was incorrectly marked. This issue has no implication on performance, safety or environment.

Affected vehicle owners will be receiving communication from Maruti Suzuki authorized workshops for vehicle inspection and necessary rectification, if wheel rim size marking is found incorrect.

Customers can also visit the 'Imp Customer Info' section on the Company website www.marutisuzuki.com and fill in their vehicle chassis number (MA3 followed by 14-digit alpha-numeric number) to check if their vehicle needs any attention in this regard. The chassis number is embossed on the vehicle ID plate and is also mentioned in the vehicle invoice/registration documents.